INSTALLATION - SERVICE INSTRUCTIONS

765 South Pierce Avenue Louisville, Colorado 80027

303-665-6901 Phone 800-525-1963 www.markwilliams.com



Bulletin #103 page 1 of 3

71900 BRAKE KIT

August '19

PART NUMBERS:

DESCRIPTION

71900... F350 Hub Brake Kit (Pair) (For use wth 50290/50295 Weld Cups)

PARTS INCLUDED:

2X - 71028...Brake Hat

2X - 71029...14" Solid Brake Disc With Cleaning Grooves

2X - 71031...Caliper Mount Bracket

16X - 71033...Bolt, 12 Point 5/16" - 24

16X - 71037...Drive Button

2X - 81100-F350...4 Piston Caliper Assembly

4X - 81130-F350...High Friction Brake Pad

4X - AN122584...3/8" Washer .078" Thick

4X - AN6-10A...Bolt, 3/8" - 24

4X - 219.14.60.1.50...14MM X 1.5 - 60MM Socket Cap Screws

4X - 227.14.28WA... 14MM Washers

PARTS NOT INCLUDED:

SP940200 Timken F350 Hub 2005-2010.

Hubs can be sent to MWE for redrilling if non-standard hole patterns are required. 50294 Hub Cover and 50291/50298 Axles are sold seperately in 50255/50265 EZ Align Axle Kit.



Rock Crawling, Ultra4, General Off-Road Use


ASSEMBLY OVERVIEW:

- 1) If using MW EZ Align Axle Kit 50255/50265, complete steps #1-3 of service bulletin #102 before starting this assembly.
- **2)** Align caliper bracket at either a 12:00, 3:00, or 9:00 position. Thread two 14MM X 1.5 60MM bolts through the caliper bracket, weld cup, and into the hub using the included washers. Thread two 14MM X 1.5 50MM bolts through the two remaining holes in the weld cup. The calipers will need to be at either a 3:00 or 9:00 position to be bled properly.
- 3) Slide drive buttons into the brake disc. Lay brake hat on top of rotor and use 71033 bolts to secure the hat to the rotor. See Figure 1 for orientation. Use small drop of #271 red thread locking compound
- 4) Slide rotor and brake hat assembly over the wheel studs. The ID of the brake hat will register on the hub and the inside face will be flush against the hub.
- 5) Install brake pads in caliper assembly. Bolt caliper assembly to caliper mount. Ensure centerline of brake caliper assembly is in line with the centerline of the rotor. See service bulletin #86 for general brake installation.
- 6) If using MW EZ Align Axle Kit 50255/50265, continue on to step #5 of service bulletin #102.

TORQUE SPECS:

Rotor attachment bolts (5/16-24 12 point bolts) 25 ft/lbs. with #271 red thread locking compound Caliper mounting bolts (3/8-24 AN bolts) 35 ft/lbs.

Weld Cup bolts (14MM X 1.5 bolts) 60 ft/lbs.



INSTALLATION - SERVICE INSTRUCTIONS

765 South Pierce Avenue Louisville, Colorado 80027

303-665-6901 800-525-1963 www.markwilliams.com



Bulletin #103 page 2 of 3

71900 BRAKE KIT

August '19




Figure 1: Drive Button Orientation

